

October 12, 1981

Mr. J. G. Keppler, Regional Director Office of Inspection and Enforcement, Region III U. S. NUCLEAR REGULATORY COMMISSION 799 Roosevelt Road Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

DOCKET NO. 50-266
LICENSEE EVENT REPORT NO. 81-013/03L-0
POINT BEACH NUCLEAR PLANT, UNIT 1

Enclosed is Licensee Event Report No. 81-013/03L-0

(a 30-day report) with an attachment which provides a

description of an event reportable in accordance with

Technical Specification 15.6.9.2.B.3, "Observed inadequacies
in the implementation of administrative or procedural controls
which threaten to cause reduction of degree of redundancy
provided in reactor protection systems or engineered safety
feature systems".

Very truly yours,

C. W. Fay, Director Nuclear Power Department

Enclosure

Copy to NRC Resident Inspector

1823/1