

PHILADELPHIA ELECTRIC COMPANY

2301 MARKET STREET P.O. BOX 8699 PHILADELPHIA, PA. 19101 (215) 841-4000

October 21, 1981

Director Office of Nuclear Reactor Regulations U.S. Nuclear Regulatory Commission Washington, DC 20555



Dear Director:

Enclosed are revisions to pages 90 and 91 of the Reactor Containment Building Integrated Leak Rate Test Report, dated April 4, 1977.

The revisions, indicated by a vertical bar in the margin, are as follows:

- Page 90 the September 14, 1975 test data for penetrations N231 A & B was not included in the report.
- Page 51 the test on MSIV 80B was incorrectly reported as taking place on December 29, 1976. The correct data should be December 26, 1976 with 282 SCCM leakage.

Very truly yours,

10. M. Alde

W. M. Alden Engineer-in-Charge Nuclear Section Generation Division

cc: Mr. R. C. Haynes, Director Region I Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, PA 19406

> Mr. Norman Haller Office of Management and Program Analysis U.S. Nuclear Regulatory Commission Washington, DC 20555

Mr. K. Cowgill Resident Inspector