

OCT 29 1981

Providence Hospital  
ATTN: Mr. Richard Stanko  
Administrator  
16001 W. Nine Mile Road  
Southfield, MI 48037

License No. 21-02802-02  
License No. 21-02802-03

Gentlemen:

This refers to the routine safety inspection conducted by Mr. R. E. Burgin of this office on October 14 and 16, 1981, of activities authorized by NRC Byproduct Material Licenses No. 21-02802-02 and No. 21-02802-03 and to the discussion of our findings with you and Mr. Ronald A. Rocchio at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities under License No. 21-02802-03 appeared to be in noncompliance with NRC requirements, as specified in enclosed Appendix A. A written response, submitted under oath or affirmation, is required. No items of noncompliance were identified for License No. 21-02802-02.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

D. J. Sreniawski, Chief  
Materials Radiation Protection  
Section 2

Enclosure: Appendix A,  
Notice of Violation

cc w/encl:  
DMF Document Control Desk (RIDS)

RIII  
Burgin/jp  
10/28/81

RIII  
Sreniawski  
10/29/81

8111060451 811029  
NMS LIC30  
21-02802-02 PDR



1209  
3/11