50.55(e) Report

## Southern California Edison Company

SCE

P O BOX 800 2244 WALNUT GROVE AVENUE ROSEMEAD CALIFORNIA 91770

October 26, 1981

TELEPHONE (213) \$72-1695

Mr. R. H. Engelken, Director Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission Region V Suite 202, Walnut Creek Plaza 1990 North California Boulevard Walnut Creek, California 94506

Dear Mr. Engelken:

J. M. CURRAN

MANAGER, QUALITY ASSURANCE

m

Subject: Docket Nos. 50-361 and 50-362

San Onofre Nuclear Generat: Station, Units 2 & 3

This letter confirms verbal notification on October 23, 1981 of a condition discovered in construction which is considered potentially reportable in accordance with 10CFR50. 55(e). This condition involves reflector indications noted during Ultrasonic testing performed for Preservice Examination (PSE) of the Reactor Pressure Vessel for Unit 3 in accordance with ASME BPV Code, Section XI. These indications may be rejectable indications under the PSE criteria which is used for establishing a baseline for inservice inspection.

We are performing an evaluation of the condition and will submit a report in accordance with 10CFR50.55(e) if the evaluation concludes that reportability criteria are met. If you have any questions or require additional information, please let me know.

Very truly yours,

J. M. Curron

cc: Dr. L. T. Papay
A. E. Chaffee (NRC, San Onofre Units 2 & 3)

NOV -2 PN ID: 34

8111130357 811026 PDR ADOCK 05000361 S PDR