


November 3, 1981

Mr. J. G. Keppler, Regional Director Office of Inspection and Enforcement, Region III U. S. NUCLEAR REGULATORY COMMISSION 799 Roosevelt Road Glen Ellyn, Illinois 60137



Dear Mr. Keppler:

DOCKET NO. 50-301 LICENSEE EVENT REPORT NO. 81-008/01T-0 POINT BEACH NUCLEAR PLANT, UNIT 2

Enclosed is Licensee Event Report No. 81-008/01T-0 (a 14-day follow-up report) with an attachment which provides a description of an event reportable in accordance with Technical Specification 15.6.9.2.A.6, "Personnel error or procedural inadequacy which prevents, or could prevent by itself, the fulfillment of the functional requirements of systems required to cope with accidents analyzed in the FFDSAR".

Very truly yours,

C. W. Fay, Director Nuclear Power Department

Enclosure

Copy to NRC Resident Inspector

8111130639 PDR ADOCK

NOV 6 1981 5.1.