

LICENSEE EVENT REPORT

CONTROL BLOCK 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 N J S G S 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 20 26 LICENSE TYPE 30 31 CAP 32

CONT
01 REPORT SOURCE 1 6 0 3 0 0 0 2 7 2 7 1 0 1 7 8 1 8 1 1 1 1 2 8 1 9
7 8 REPORT SOURCE 60 61 DCKET NUMBER 66 69 EVENT DATE 74 75 REPORT DATE 81

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 On two occasions, October 17 and October 29, 1981, each following a reactor trip,
03 the Auxiliary Feed Storage Tank dropped below the minimum required volume of 200,000,
04 gallons due to steam generator makeup. At 1456 and 1358 hours, on October 17 and 29,
05 respectively, the Auxiliary Feed Storage Tank was declared inoperable, and Action
06 Statement 3.7.1.3.a was entered.

07
08
09
SYSTEM CODE SH 11 CAUSE CODE X 12 CAUSE SUBCODE Z 13 COMPONENT CODE ACCUMU 14 COMP SUBCODE Z 15 VALVE SUBCODE Z 16
17 LEAD REPORT NUMBER 18 EVENT YEAR 81 19 SHUTDOWN METHOD Z 20 HOURS 0000 21 ATTACHMENT SUBMITTED Y 22 NPD-4 FORM SUB N 23 PRIME COMP SUPPLIER L 24 COMPONENT MANUFACTURER X999 25
ACTION TAKEN X 26 FUTURE ACTION Z 27 EFFECT ON PLANT Z 28 SHUTDOWN METHOD Z 29 HOURS 0000 30 ATTACHMENT SUBMITTED Y 31 NPD-4 FORM SUB N 32 PRIME COMP SUPPLIER L 33 COMPONENT MANUFACTURER X999 34

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 Demineralized water was transferred to the Auxiliary Feed Storage Tank and the
11 volume was restored to greater than the minimum specification of 200,000 gallons.
12 At 1845 and 1617 hours, respectively, the Auxiliary Feed Storage Tank was declared
13 operable and Action Statement 3.7.1.3.a was terminated.

14
15 FACILITY STATUS D 28 % POWER 0000 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Observation 32
16 ACTIVITY CONTENT Z 33 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36
17 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39
18 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION N/A 41
19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43
20 PUBLICITY ISSUED N 44 DESCRIPTION N/A 45

8111230334 811112
PDR ADOCK 05000272
S PDR

Frank Dickey

PHONE: 609-935-5100