DCS No: Date:

50247-811111 November 12, 1981

## PRELIMINARY NOTIFICATION OF EVENT OR UNUSUAL OCCURRENCE--PNO-I-81-123

This preliminary notification constitutes EARLY notice of events of POSSIBLE safety or public interest significance. The information is as initially received without verification or evaluation, and is basically all that is known by IE staff on this date.

Facility: Consolidated Edison Company of New York, Inc.

Indian Point Unit 2 (DN 50-247)

Buchanan, New York

Licensee Emergency Classification: Notification of Unusual Event

Alert

Site Area Emergency General Emergency

Not Applicable

Subject: UNIT SHUTDOWN TO REPAIR RCP SEAL

The unit shutdown at 8:59 p.m., on 11/11/81 to repair the No. 1 seal on Peactor Coolant Pump No. 23. Excessive leakage past the No. 1 seal was detected at 8:38 p.m., 11/11. No leakage to the containment occurred. As of 8:00 a.m., 11/12/81, the unit is proceeding to cold shutdown for an outage expected to last 7-10 days.

The NRC will not issue a press release, however, the licensee issued a press release on 11/11/81.

The State of New York has been informed.

Region I (Philadelphia) received notification of this occurrence by telephone from the

Senior Resident Inspector at 8:15 a.m., 11/12/81.

CONTACT: J. Wiggins 488-1382

T. Rebelowski 914-739-9360

W. Baunack 914-739-9360

DISTRIBUTION:

H. St. 10:26 Chairman Palladino Comm. Gilinsky Comm. Bradford

Comm. Ahearne Comm. Roberts

ACRS SECY CA

MNBB 10:31 EDO AEOD

PA

MPA

ELD

Phillips/0132 NRR

Air Rights 10:30

E/W 10:24

NMSS RES

Willste 10,34 Landow OIA

INPO 10: 44

MAIL: IE: TAS

NSAC / 0149 ADM: Doc. Mgt. Br.

TMI Resident Section 10.54 RI Resident Office 12:53

Region I Form 83 (Rev. Oct. 16, 1981) Destroyed previous edition

8111230542 811112 PDR I&E PNO-V-81-123 PDF PDR