



November 18, 1981

Log No. K81-162  
File: RR 2 (NP-33-81-80)

Docket No. 50-346  
License No. NPF-3

Mr. James G. Keppler  
Regional Director, Region III  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137



Dear Mr. Keppler:

Reportable Occurrence 81-067  
Davis-Besse Nuclear Power Station Unit 1  
Date of Occurrence: October 22, 1981

Enclosed are three copies of Licensee Event Report 81-067 with a supplemental information sheet which are being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Terry D. Murray  
Station Superintendent  
Davis-Besse Nuclear Power Station

TDM/ljk

Enclosure

cc: Mr. Victor Stello, Jr., Director  
Office of Inspection and Enforcement  
Encl: 30 copies

Mr. Norman Haller, Director  
Office of Management and Program Analysis  
Encl: 3 copies

Mr. Luis Reyes  
NRC Resident Inspector  
Encl: 1 copy

8111300417 811118  
PDR ADOCK 05000346  
S PDR