## YANKEE ATOMIC ELECTRIC COMPANY (YAEC) CONTROLLED DOCUMENT REVISION TRANSMITTAL FORM

IMS	SUBJECT NO. A15.1.3/V2.2.12 RECORD TYPE NO. 10.E.06.001	
	y NUMBER 19 (9)	
	VIETTIS .	
	Notalita &	
	NDMENT NUMBER (if applicable):	1
ASS	IGNED HOLDER: NRC-NRK - NOV1 6 1981-	
ISS	UE DATE: NOVEMBER 10, 1981 COMMISSION	
	ached is an authorized revision to the above listed document, for a serion into your assigned copy.	
1.	Incorporate this change in the above document.	
2.	Sign the Yankee Atomic Electric Company (YAEC) Controlled Document Record of Changes in the front of your document.	
3.	Sign this form and return it to the address below.	
4.	Response is expected within 10 working days of the issue date.	
	Final Response Date: NOVEMBER 25, 1981	
	Transmitted By: DELORES I. MARKT	
	THE UNDERSIGNED ACKNOWLEDGES COMPLETION OF THE FOLLOWING ACTIONS.	
1.	The receipt and incorporation of change number 6 in the above document.	
2.	The review of the revised material.	
3.	Assurance that those who use the document are aware of the change.	
4.	The completion of the YAEC Controlled Documen. Record of Changes in the front of the document.	
5.	Destruction of all superseded pages.	
Sig	nature of Holder: Date:	
Ret	Library Yankee Atomic Electric Company 1671 Worcester Road Framingham, Massachusetts 01701	
	805000271 PDR -3- X005	9.4

Change #6

## - Instructions -

- Under the tab "Table of Contents" remove the table of contents and insert the attached table of contents dated November 5, 1981.
- Under the tab "Classification of Emergencies" remove the procedure numbered A.P. 3125, Rev. 1 and insert the procedure numbered A.P. 3125, Rev. 2.
- 3. Under the tab "Emergency Plan Training" remove the procedure numbered O.P. 3712, Rev. 4 and insert the procedure numbered O.P. 3712, Rev. 5.
- 4. Under the tab "Emergency Equipment Check" remove the procedure numbered O.P. 3506, Rev. 12 and insert the procedure numbered O.P. 3506, Rev. 13.
- 5. Under the tab "Coordination and Communications" incorporate the Department Instructions 81-20 and 81-21 into the procedure numbered 0.P. 3504, Rev. 13.