



Public Service Electric and Gas Company P.O. Box 168 Hancocks Bridge, New Jersey 08038

Salem Generating Station

September 4, 1981

Mr. R. C. Haynes  
Director of USNRC  
Office of Inspection and Enforcement  
Region 1  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Dear Mr. Haynes:

REPORTABLE OCCURRENCE 81-86/01P  
SALEM NO. 2 UNIT LER

This letter is to confirm our verbal report to the NRC Resident Inspector on Friday, September 4, 1981, advising of a potential reportable occurrence in accordance with Technical Specification 6.9.1.8.b.

At 1610 hours, September 3, 1981, No. 21 steam generator steam flow channels 1 and 2 were declared inoperable due to being out of calibration. A unit shutdown was commenced and the inoperable channels were placed in the tripped condition. Both channels have been recalibrated satisfactorily and returned to service.

A detailed report will be submitted in the time period specified by Technical Specification 6.9.1.8.b.

Sincerely yours,

A handwritten signature in cursive script, appearing to read "H. J. Midura".

H. J. Midura  
Manager - Salem Generating Station

RHM:slg

CC: General Manager - Nuclear Production  
General Manager - Quality Assurance