1000 000

NRC FORM 591 PART 1

U.S. NUCLEAR REGULATORY COMMISSION

(7-91) 10 CER 2.201	SAFETY INSPE	ECTION	Page 1 of
Abbott Health Pr Vega Alta, P.R	oducts	101 MARI	II LEAR REGULATORY COMMISSION ETTA STREET NW SUITE 2900 GA 30323
3. DOCKET NUMBER(S) 30 - 3057 8	4. LICENSE NUMBER(S) 5-2-24994		6/8/92
Regulatory Commission (NRC) rules and regulatory	lations and the conditions of your lie	pense. The inspe	radiation safety and to compliance with the Nuclear action consisted of selective examinations of or. The findings as a result of this inspection are as
questions on those actions at this ti	you have taken to correct the violat me.	tached, were in a	uring the last inspection. We have no further violation of NRC requirements. This form is a
A			was not properly posted to
indicate the presence of a			. 10 CFR 20.203(h),(c),(d),(e) or 34.42.
В			of sealed sources were not
performed at the proper frequency	uencies, 10 CFR	or License C	Condition Number
C. Records of			were not properly maintained.
10 CFR	or License Condition Number		
D. Documents were not properly	posted or otherwise made available	. 10 CFR 19.11.	
E. Reports or notification of			were not made in accordance with
10 CFR	or License Condition Number		
F			
I hamby state that within 20 days the actions	described by one to the lengester w	Ill for Antonio to me	most the Colodon Monthley to the Bear Street

above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.

SIGNATURE - LICENSEE 150026 DATE

9303150245 920608 PDR ADOCK 33000578 C PDR

SIGNATURE— NAC INSPECTOR