SAFETY INSPECTION

10 GFR 2.201

Page 1 of

1. LICENSEE

Standard Laboratories, Inc. 4815 MacCorkle Avenue, S.E. Charleston, West Virginia 25304

1. Within the scope of this inspection, no violations were observed.

2. REGIONAL OFFICE

REGION II U.S. NUCLEAR REGULATORY COMMISSION 101 MARIETTA STREET NW SUITE 2900 ATLANTA GA 30323

3. DOCKET NUMBER(S)

4. LICENSE NUMBER(S)

or License Condition Number

DATE

5. DATE OF INSPECTION

7/30/92

LICENSEE

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

] 2	The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions an those actions at this time.		
] 3		g this inspection certain of your activities, as described below or attached, were in violation CE OF VIOLATION, which is required to be posted in accordance with 10 CFR 19.11.	of NRC requirements. This form is a
Γ	A		was not properly posted to
house	totamen.	indicate the presence of a	10 CFR 20.203(b),(c),(d),(e) or 34.42.
П	В.		of sealed sources were not
Season	no.com	performed at the proper frequencies. 10 CFR or License Condition	Number
	C.	Records of	were not properly maintained.
Secure		10 CFR or License Condition Number	
Г	D.	Documents were not properly posted or otherwise made available. 10 CFR 19.11.	
process .			
	E.	Reports or notification of	were not made in accordance with

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2:201. No further response will be submitted

unless required by the NRC SIGNATURE - LICENSEE

9303150283 920730 ADOCK 03032767

150038

SIGNATURE - NRC INSPECTOR

Jerry D. Ennis