

UNITED STATES

## NUCLEAR REGULATORY COMMISSION

**REGION IV** 

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064

## MAY 2 0 1993

Docket: 030-12376 License: 42-09073-02

Tennessee Gas Pipeline Company ATTN: D. L. Culbertson Radiation Safety Officer 5510 South Rice Avenue Houston, Texas 77081

SUBJECT: NRC INSPECTION REPORT 030-12376/93-01

This refers to the routine, unannounced inspection conducted by Mr. Richard A. Leonardi, Jr., of this office on May 10, 1993. The inspection included a review of activities authorized by Byproduct Material License 42-09073-02. At the conclusion of the inspection, the findings were discussed with members of your staff.

The inspection was an examination of activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, and observation of activities in progress.

No violations or deviations were identified; therefore, no response to this letter is required.

The inspector noted that the licensee had conducted radiography in NRC jurisdiction in Pennsylvania on 15 separate occasions between May 18, 1992, and June 9, 1992, and also in the state of Ohio on one occasion on September 16, 1992. The inspector determined that the licensee had audited the radiographer and the assistant radiographer involved in activities in both of these states at the required 3-month interval as determined by a review of records maintained by the licensee. A review of licensee records indicated that alarm ratemeters had been used by radiography personnel on all jobs for the period under review.

The inspector was not able to observe the licens or mradiography during the course of this inspection.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter will be placed in the NRC Public Document Room.

305260044 93052 PDR ADOCK 03012376 PDR

IECI

Tennessee Gas Pipeline Company -2-

Should you have any questions concerning this letter, please contact the inspector identified above at (817) 860-8100.

Sincerely,

Charles X. Coin

Charles L. Cain, Chief Nuclear Materials Inspection Section

CC:

.

Texas Radiation Control Program Director

Tennessee Gas Pipeline Company -3-

bcc: DMB - Original (IE-07) JLMilhoan LJCallan DDChamberlain MRodriguez, OC/LFDCB (4503) \*WLFisher \*CLCain \*RALeonardi \*NMIS \*MIS System \*RIV Files (2) \*REHall, URFO

\*W/IFS Form

.

RIV: NMIS ROL	C:NMISORO	
RALeonardi	CLCain	
05/19/93	05/20/93	

Tennessee Gas Pipeline Company -3-

bcc: DMB - Original (IE-07) JLMilhoan LJCallan DDChamberlain MRodriguez, OC/LFDCB (4503) \*WLFisher \*CLCain \*RALeonardi \*NMIS \*MIS System \*RIV Files (2) \*REHall, URFO

\*W/IFS Form

.

RIV: NMIS ROZ	C:NMISULA	
RALeonardi	CLCain	
05/19/93	05/20/93	

250006