



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROCSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

Docket No. 50-10/77-33
Docket No. 50-237
Docket No. 50-249

16 1977

Commonwealth Edison Company
ATTN: Mr. Byron Lee, Jr.
Vice President
P.O. Box 767
Chicago, IL 60690

POOR ORIGINAL

Gentlemen:

This refers to the inspection conducted by Mr. W. D. Shafer of this office on November 10, 11, 15-18, and 22-23, 1977, of activities at Dresden Nuclear Power Station, Units 1, 2, and 3, authorized by Licenses No. DPR-2, No. DPR-19, and No. DPR-25 and to the discussion of our findings with Mr. B. B. Stephenson at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in noncompliance with NRC requirements, as described in the enclosed Appendix A. Regarding noncompliance No. 5 in Appendix A, the inspection showed that action had been taken to correct the identified noncompliance and to prevent recurrence. Consequently, no reply to noncompliance No. 5 is required and we have no further questions regarding this matter at this time.

In addition to your response on the individual items of noncompliance, we request that your response address what additional steps will be taken with respect to your equipment outage control system to preclude events such as those cited in Appendix A, items 1 through 4.

This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you

8009030

759

7

Commonwealth Edison
Company

- 2 -

DEC 16 1977

to submit to this office within twenty days of your receipt of this notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC's Public Document Room, except as follows. If the enclosures contain information that you or your contractors believe to be proprietary, you must apply in writing to this office, within twenty days of your receipt of this letter, to withhold such information from public disclosure. The application must include a full statement of the reasons for which the information is considered proprietary, and should be prepared so that proprietary information identified in the application is contained in an enclosure to the application.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

James G. Keppler
Director

Enclosures:

1. Appendix A, Notice of Violation
2. IE Inspection Reports
No. 50-010/77-35;
No. 50-237/77-32;
and No. 50-249/77-30

cc w/encs:

Mr. B. B. Stephenson, Station
Superintendent
Central Files
Reproduction Unit NRC 20b
PDR
Local PDR
NSIC
TIC
Anthony Reisman, Esq.,
Attorney

OFFICE	RIII	RIII	RIII	RIII	RIII
SURNAME	Shafer/jb	Knop <i>gck</i>	Fiorella <i>gck</i>	Notarius <i>gck</i>	Keppler <i>gck</i>
DATE	12/9/77 <i>gck</i>			12/15/77	

POOR ORIGINAL