REDITTION TO A SECURE OF THE PERSONS 1 CARLES AND CARLON

. .

HARTFORD, GOMNECTHE TIS

November 5, 1980 MP-1-1651 80 HOV 10 PM PP 13

Mr. Soyce H. Brier Director, Region I Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia. PA 19406

Reference:

Provisional License OPR-21 Docket No. 50-246 Roportable Occurrence RO-80-18/19

Dear Mr. Grier:

This lotter is forwarded to provide prompt notification of Reportable Occurrence RO-30-18/1P as required by the Millstone Unit 1 Technical Specifications.

On November 5, 1980 at 0930 hours, two (2) main steam line support members (MSRH-32 and MSRH-28) were found to have failed welds between the support members and the support structure. The cause of failure is not known at the present time; an investigation is in progress.

Additional information including the cause of failure and corrective action will be included in a 14 day follow-up report.

Yours truly.

NORTHEAST NUCLEAR ENERGY COMPANY

>quelecte

Mroczka Station Superintendent Milistone Nuclear Power Station

EJM/MJB: kaf

Director, Office of Management Information and Program Control, Washington, D.C. (2)
U.S. Nuclear Regulatory Commission, c/o Document Management
Branch, Washington, D.C. 20555

8011200 311

LICENSEE EVENT REPORT

	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
0 1 7 8	SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
0 2	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 3	SEE Afforhad LEHEZ
0 4	
0 5	
0 6	
0 7	
08	9 SYSTEM CAUSE CAUSE COMP. VALVE
0 9	SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBC
	TO REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
	ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT METHOD HOURS 22 SUBMITTED FORM SUB. SUPPLIER MANUFACTURER
	18 19 36 20 36 21 37 40 41 23 42 24 43 25 44 47 21 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0	
1 1	
1 2	
1 3	
1 4	9 80 FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32
1 6	28 1 29 31 44 45 31
	ACTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36 10 10 11 44 45
1 7	PERSONNEL EXPOSURES NUMBER TYPE 37 38 DESCRIPTION 39
1 B	PERSONNEL INJURIES NUMBER DESCRIPTION (1)
1 9	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION 42
20	PUBLICITY ISSUED DESCRIPTION 45
8	9 10 68 59 80 5 NAME OF PREPARER