Consolidated Edison Company of New York, Inc. 4 Irving Place, New York, N Y 10003 Telephone (212) 460-3819

January 23, 1978
Indian Point Station
Docket No. 50-247

Mr. Walter G. Martin, Chief Safeguards Branch U.S. Nuclear Regulatory Commission Region I 631 Park Avenue King of Prussia, Pennsylvania 19406

Dear Mr. Martin

This refers to Inspection 50-247/77-37 conducted by Messrs. E. Jones and R. Bailey, Physical Protection Inspectors, on November 13-15, 1977, of activities authorized by NRC License No. DPR-26 at Indian Point Station. Your December 20, 1977, letter stated that it appeared that certain of our activities were not conducted in full compliance with NRC requirements, these were set forth in the Notice of Violation enclosed therewith as Appendix A. Our response to these items of noncompliance-presented in the attached Appendix A - is being submitted at this time in accordance with a January 6, 1978 telephone conversation between Mr. John Streeter, Reactor Inspector, and our Mr. John Makepeace in which a request for a two week extension of the reply date was approved.

In accordance with Section 2.790(d) of the NRC's Rules of Practice, Part 2, Title 10, Code of Federal Regulations, correspondence and reports to or from the NRC which identify a licensee's control and accounting procedures for safeguarding licensed special nuclear material or detailed security measures for the physical protection of a licensed facility, are exempt from disclosure. We understand therefore that this letter will not be placed in the Public Document Room and will receive limited distribution.

Very truly yours

William Halilly.