



Iowa Electric Light and Power Company

November 10, 1981

DAEC-81-416

Mr. James G. Keppler, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

PRINCIPAL STAFF	
DIR	has
D/D	BAO
A/D	ALO
ORAPI	
DESTI	has
DEP&OS	File

orig + 1

Re: Duane Arnold Energy Center

Subject: Unique Report 81-4, 1981 Local Leak Rate Tests

File: A-110, R/T-1

Dear Mr. Keppler:

In accordance with DAEC Technical Specification 6.11.3.d, please find enclosed for your review copies of the Reactor Containment Local Leak Rate Test report for Type B and C tests conducted at the DAEC during the 1981 refueling outage.

Very truly yours,

Daniel L. Mineck
Chief Engineer
Duane Arnold Energy Center

DLM/JVS/p1

Enclosures

cc: NRC Resident Inspector - DAEC
L. Root
D. McGaughy
B. York
J. Vinquist
J. Hurley

8112140243 811110
PDR ADOCK 05000331
PDR

NOV 17 1981

Handwritten: 28
1E 510