

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

USNRC REGION II
ATLANTA, GEORGIA

31 DEC 4 PM 2:34

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

November 30, 1981

TELEPHONE AREA 704
373-4083


Mr. J. P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 1
Docket No. 50-369

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/81-172. This report concerns T.S.3.3.1, "As a Minimum, the Reactor Trip System Instrumentation Channels and Interlocks of Table 3.3-1 Shall be Operable . . .". This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,


William O. Parker, Jr.

PBN/smh

Attachment

cc: Director
Office of Management and Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Records Center
Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

Mr. P. R. Bemis
Sr. Resident Inspector-NRC
McGuire Nuclear Station



OFFICIAL COPY

8112140307 811130
PDR ADOCK 05000369
S PDR

IE22
5
1/1