

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION.)

CONT
0 1
REPORT SOURCE 1 6 0 5 0 0 0 2 7 2 7 1 1 0 8 8 1 6 1 2 0 2 8 1 6
80 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

Channel 3 failed high. Channel 3 was declared inoperable and Action Statement

3.3.2.1 Action 14 was entered at 1942 hours.

0 6

6

67

CONFIDENTIAL

SYSTEM CODE I B 11		CAUSE CODE E 12		CAUSE SUBCODE E 13		COMPONENT CODE I N S T R U 14				COMP SUBCODE Y 15		VALVE SUBCODE Z 16	
EVENT YEAR 8 1 21		SEQUENTIAL REPORTING 1 1 3 24		OCCURRENCE CODE 0 3 28		REPORT TYPE L 30		REPAIR NO. 0 31		ACTION TAKEN C 18		FUTURE ACTION Z 19	
EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22		ATTACHMENT SUBMITTED Y 23		NPRM FORM SUB Y 24		PRIME COMP SUPPLIER L 25		COMPONENT MANUFACTURER H 0 2 0 3	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (2)

10 The cause of the inoperable channel was the failure of the dual comparator. The

comparator was replaced and tested satisfactorily and Action Statement 3.3.2.1

1 2 | Action 14 was terminated at 2210 hours.

1	3	
---	---	--

1	4	
---	---	--

7 8 9
FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)
1 5 E (28) 0 8 0 (29) N/A A (31) Operator Observation

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 2 33 2 34

AMOUNT OF ACTIVITY (35)

N/A

LOCATION OF RELEASE (35)

N/A

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	37	Z	3E	N/A	

		PERSONNEL INJURIES			DESCRIPTION	
		11	12	13		
		NUMBER				
1	R	0	0	0	41	N/A

8		9		11		12	
LOSS OF OR DAMAGE TO FACILITY (43)							
TYPE		DESCRIPTION					
1	9	2	42	N/A			

3 8 9 10 PUBLICITY (45) B112140349 B11202
ISSUED DESCRIPTION (44) N/A PDR ADDCK 05000272 PDR NRC USE ONLY
2 0 N 44 68 69 70

NAME OF PREPARER

Ken Whitcomb

PHONE

609-935-0998