Docket No. 50-029 LS05-81-12-037

> Mr. James A. Kay Senior Engineer - Licensing Yankee Atomic Electric Company 1671 Worcester Road Framingham, Massachusetts 01701

Dear Mr. Kay:

SUBJECT: SYSTEMATIC EVALUATION PROGRAM TOPIC V-7, REACTOR

COOLANT PUMP OVERSPEED - YANKEE ROWE

Topic V-7, "Reactor Coolant Pump Overspeed" is a generic topic being resolved under NRR Generic Issue B-68, "Pump Overspeed during LOCA." The concern is that if a reactor coolant pump assembly is driven to a speed which would cause structural failure of the unit, it could result in missiles which could increase the consequences of the LOCA. Of greatest concern is the pump flywheel. Since Yankee Rowe has no pump flywheel, but is a canned rotor pump, Topic V-7 has been deleted for Yankee Rowe.

Sincerely,

Dennis M. Crutchfield, Chief Operating Reactors Branch No. 5 Division of Licensing

cc: See next page

OFCI 5 1981

5E04 1/1 DSU WS (11) ADD; Wang

8112160-349

SURNAME	SEPB:DL AWang:dk	RHermann	SEPB:DL WRussell 12/ 8/81	RCaruso	DCrutchfie	d GLainas	
NRC FORM 318 (10-80) NRCM 0240			OFFICIAL RECORD COPY				USGPO: 1981535-960

cc Mr. James E. Tribble, President Yankee Atomic Electric Company 25 Research Drive Westborough, Massachusetts 01581

Greenfield Community College 1 College Drive Greenfield, Massachusetts 01301

Chairman
Board of Selectmen
Town of Rowe
Rowe, Massachusetts 01367

Energy Facilities Siting Council
14th Floor
One Ashburton Place
Boston, Massachusetts 02108

U. S. Environmental Protection
Agency
Region I Office
ATTN: Regional Radiation Representative
JFK Federal Building
Boston, Massachusetts 02203

Resident Inspector Yankee Rowe Nuclear Power Station c/o U.S. NRC Post Office Box 28 Monroe Bridge, Massachusetts 01350