


December 14, 1981

DJS Ltr. #81-984

James G. Keppler, Regional Director
Directorate of Regulatory Operations - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Reportable Occurrence Report #81-39/01T-0, Docket 050-249 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.1.(e), failure or malfunction of one or more components which prevents or could prevent, by itself, and the fulfillment of the functional requirements of system(s) used to cope with accidents analyzed in the SAR.


for D. J. Scott
Station Superintendent
Dresden Nuclear Power Station

DJS:nh

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
U.S. NRC, Document Management Branch
File/NRC



DEC 15 1981

8112220233 811214
PDR ADOCK 05000249
S PDR

IE22
11