



December 29, 1981

Log No. K81-375  
File: RR 2 (NP-33-81-91)

Docket No. 50-346  
License No. NPF-3

Mr. James G. Keppler  
Regional Director, Region III  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137



Dear Mr. Keppler:

Reportable Occurrence: 81-076  
Davis-Besse Nuclear Power Station Unit 1  
Date of Occurrence: November 30, 1981

Enclosed are three copies of Licensee Event Report 81-076 including a supplemental information sheet which are being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

*Terry D. Murray*

Terry D. Murray  
Station Superintendent  
Davis-Besse Nuclear Power Station

TDM/ljk

Enclosure

cc: Mr. Victor Stello, Jr., Director  
Office of Inspection and Enforcement  
Encl: 30 copies

Mr. Norman Haller, Director  
Office of Management and Program Analysis  
Encl: 3 copies

Mr. Luis Reyes  
NRC Resident Inspector  
Encl: 1 opy

8201110024 811229  
PDR ADOCK 05000346  
S PDR

*IE22  
S11*