


12/22/81

License: 25-01203-01

Department of Health, Education and Welfare
ATTN: Robert F. Bergman
Radiation Safety Officer
903 South 4th
Hamilton, MT 59840



Gentlemen:

This refers to the routine safety inspection conducted by Mr. R. Wise of this office on December 3, 1981, of the activities authorized by NRC Byproduct Material License 25-01203-01 and to the discussion of our findings held by the inspector with members of your staff at the conclusion of the inspection.

The inspection was an examination of the activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations, and the conditions of the license. The inspection consisted of selected examinations of procedures and representative records, interviews of personnel, independent measurements, and observations by the inspector.

No violations of NRC requirements were found during this inspection.

Mr. Wise also reviewed the action you had taken with respect to one violation observed during our previous inspection, which was conducted February 8, 1979. He verified that the corrective action with respect to this item was implemented as stated in your reply of March 13, 1979, to our letter dated February 22, 1979.

Should you have any questions concerning this letter, we will be pleased to discuss them with you.

Sincerely,

8201130013 811222
NMSSLIC30
25-01203-01 PDR

Glen D. Brown, Chief
Technical Inspection Branch

IE-07
510

bcc: C/o DMB
AEOD IEFiles IE/RSB NMSS NRC PDR

OFFICE	TIB	MRPS	IES	RA	TIB-RIV		
SURNAME	RWise/de	JEVerett	JGagliardo	JPollins	GDBrown		
DATE	12/16/81	12/17/81	12/21/81	12/21/81	12/17/81		