

COPIES 4
JAN 7 1982



December 30, 1981

Log No. K81-384
File: RR 2 (NP-33-81-92)

Docket No. 50-346
License No. NPF-3



Mr. James G. Keppler
Regional Administrator, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Reportable Occurrence 81-078
Davis-Besse Nuclear Power Station Unit 1
Date of Occurrence: December 3, 1981

Enclosed are three copies of Licensee Event Report 81-078 with a supplemental information sheet which are being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Terry D Murray

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/ljk

Enclosures

cc: Mr. Victor Stello, Jr., Director
Office of Inspection and Enforcement
Encl: 30 copies

Mr. Norman Haller, Director
Office of Management and Program Analysis
Encl: 3 copies

Mr. Luis Reyes
NRC Resident Inspector
Encl: 1 copy

8201130056 811230
PDR ADOCK 05000346
S PDR

JAN 7 1982

IE 22
5/11