TENNESSEE VALLEY AUTHORITY

CHAMANDOGA TENNESSEE 37401 1750 Chestnut Street Tower II

at : 11A & NAL SE

December 31, 1981

Mr. James P. O'Reilly, Director U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 - DOCKET NO. 50-260 - FACILITY OPERATING LICENSE DPR-52 - REPORTABLE OCCURRENCE REPORT BFR0-50-260/81019 - REVISION 1

The enclosed report is a supplement to my letter to you dated May 7, 1981, concerning a bypass which was installed on main steam line high temperature isolation relays to control unit conditions until the ventilation system could be returned to service or a controlled shutdown initiated and main steam isolation valves closed. This report is submitted in accordance with Browns Ferry unit 2 Technical Specification 6.7.2.a.5.

Very truly yours,

TENNESSEE VALLEY AUTHORITY


H. J. Green Director of Nuclear Power

Enclosure cc (Enclosure): Document and Control Desk U.S. Nuclear Regulatory Commission Washington, DC 20555

> Records Center Institute of Nuclear Power Operations 1820 Water Place Atlanta, Georgia 30339

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry





CARDINAL DOD

An Equal Onportunity Employer