


ARKANSAS POWER & LIGHT COMPANY POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

December 31, 1981

2CAN128105

Mr. G. L. Madsen, Chief Reactor Project Branch U. S. Nuclear Regulatory Commission Region IV 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011



Subject: Arkansas Nuclear One - Unit 2

Docket No. 50-368 License No. NPF-6 Licensee Event Report

81-045/03L-0 (File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.9.b, attached is the subject report concerning failure of a control valve to close from the control room handswitch which was discovered while in Mode 2 operation.

Very truly yours,

Davis C. Trimble

David C. Trimble Manager, Licensing

DCT: MCS: s1

Attachments

cc: Mr. Richard C. DeYoung, Director Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

> Mr. Norman M. Haller, Director Office of Management & Program Analysis U. S. Nuclear Regulatory Commission Washington, D. C. 20555

SI/1 25