

Northern Status Power Company

414 Nicollet Mall Minneapolis, Minnesota 55401 Telephone (612) 330-5500



December 16, 1981

Director, Office of Nuclear Reactor Regulation Attention Document Control Desk U S Nuclear Regulatory Commission Washington DC 20555

> MONTICELLO NUCLEAR GENERATING PLANT Docket No. 50-263 License No. DPR-22

> > EMERGENCY RESPONSE PLAN IMPLEMENTING PROCEDURES

Furnished with this letter are ten copies of a revision to the Monticello Plant Emergency Plan Implementing Procedures.

The revisions include the following procedures:

List of	Current Procedures (Dated 11/19/81)							
A.2-102	Notification of an Unusual Event	(Page	1	thru	23,	Rev	1)	
A.2-103	Alert	(Page	1	thru	24,	Rev	2)	
A.2-104	Site Area Emergency	(Page	1	thru	25,	Rev	1)	
A.2-105	General Emergency	(Page	1	thru	25	Rev	1)	
A.2-702	Response to an Emergency at P.I.	(Page	1	thru	5,	Rev	1)	
A.2-101	Classification of Emergencies	(Page	1	thru	43,	Rey	1)	
A.2-303	Search and Rescue	(Page	1	thru	11,	Rev	1)	
A.2-603	Repair and Corrective Action	(Page	1	thru	11,	Rev	0)	

These procedure documents include names and telephone numbers of the many persons having responsibility under the Emergency Plan. To maintain the confidentiality of this information for reasons of privacy and plan effectiveness, these procedure documents should not be placed in the Public Document Room or the names and telephone numbers should be deleted before placing them in the Public Document Room. We understand you appreciate this need and are in a position to accommodate the requirement.

L O Mayer, PE Manager of Nuclear Support Services

LOM/GDH/bp Encls

cc: J G Keppler (w/attachment) (3)
NRC Resident Inspector (w/o attachment)
G Charnoff (w/o attachment)

8201220247 820112 PDR ADOCK 05000263 PDR