

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

USNRC REGION II
ATLANTA, GEORGIA

1750 Chestnut Street Tower II

82 JAN 22 8 05

January 18, 1982

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE REPORT BFRO-50-259/81091

The enclosed report provides details concerning inoperability of the B control room emergency ventilation system due to FCO 31-152 not opening. This report is submitted in accordance with Browns Ferry unit 1 Technical Specification 6.7.2.b(2).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. A. Coffey
H. J. Green
Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Records Center
Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

8201290109 820118
PDR ADOCK 05000259
S PDR

ORIGINAL COPY

IE 22
S/1