SSINS No.: 6835 Accession No.: 8202040107 IN 82-04

UNITED STATES NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT WASHINGTON, D.C. 20555

March 10, 1982

IE INFORMATION NOTICE NO. 82-04: POTENTIAL DEFICIENCY OF CERTAIN AGASTAT E-7000 SERIES TIME-DELAY RELAYS

Description of Circumstances:

On February 2, 1982, the Control Profuct Division, Amerace Corporation informed the U.S. Nuclear Regulatory Commission that approximately 20 percent of their AGASTAT E-7000 Series time-delay relays manufactured during the period between July 15, 1981, to January 12, 1982, may not operate properly.


Quality Assurance tests performed to ascertain acceptable performance over extended time periods have determined that the pneumatic timing diaphragm manufactured by one of two diaphragm suppliers exhibited a bleed-out of a fluid substance as a function of time and temperature. This substance may affect the diaphragm seal on the relays operated at high temperatures for extended periods, resulting in shorter time delays than those set on the relay dial. Although the temperature required to initiate significant bleed-out would not be encountered in the majority of these relay applications, it is within the range of nuclear safety qualification tests required by IEEE-323 and IEEE-344.

In a letter dated February 2, 1982, the Control Products Division of Amerace Corporation requested users to return all of the discussed relays for inspection and possible replacements. Copies of the letter and a list of the users are enclosed. The Control Products Division records do not identify individual nuclear power plants because most shipments were made to nuclear steam supply system (NSSS) suppliers, vendors, panel manufacturers, architect engineers, and utilities.

This information notice is provided as an early notification of a potentially significant matter. It is expected that recipients will review the information for possible applicability to their facilities and take appropriate action as necessary. No specific action or response is required at this time. If you have any questions regarding this matter, please contact the Regional Administrator of the appropriate NRC Regional Office.

Attachment:

List of customers to whom applicable relays were shipped



CONTROL PRODUCTS DIVISION
AMERACE CORPORATION, 1000 HICKORY STREET
GRAFTON WISCONSIN 53024 414: 377-0800

February 2, 1982

Attachment 1 IN 82-04 March 10, 1982 Page 1 of 7

In accordance with 10CFR21 we are notifying you and the NRC of the following situation regarding some of the Agastat E7000 Series time-delay relays manufactured between the 24th week of 1981 and the 3rd week of 1982.

Extended-performance Quality Assurance tests have determined that pneumatic timing diaphragms manufactured by one of two diaphragm suppliers exhibit a time and temperature based, bleed-out of a fluid substance. This substance may affect the diaphragm seal on relays operated at high temperatures for extended periods, resulting in shorter time delays than those set on the relay dial.

Relays containing diaphragms from this supplier constituted about 20% of our production and may have been shipped to fill your purchase order(s) as listed on the attached printout.

Although the temperature required to initiate significant bleed-out would not be encountered in the majority of normal product applications it is within the range of nuclear safety related qualification tests. We are, therefore, asking you to return all E7000 relays from subject order(s), to my attention, for inspection and possible replacement. Serial numbers of all E7000 Series relays received by you during the time period concerned are attached.

Please acknowledge receipt of this notice. If you need assistance in returning the listed items, please contact me.

Yours very truly,

CONTROL PRODUCTS DIVISION

M. Q. Martin

Quality Assurance Manager

MQM/vf

1 IEEE 323 and IEEE 344

Attachment 1 IN 82-04 March 10, 1982 Page 2 of 7

GENERAL ELECTRIC COMPANY 175 Curtner Ave M/C 016 San Jose, CA 95125 Attn: Jerrold B. Morris

GENERAL ELECTRIC COMPANY Buckhorn Exit 185 - Rt 1374 P.O. Box 489 Mebane, NC 27302 Attn: QA Manager

L. K. COMSTOCK P. O. Box 1094 Monroe, MI 48161 Attn: QA Manager

SOUTH CAROLINA ELECTRIC & GAS CO. P.O. Box 764 Columbia, SC 29218 Attn: Mr. Sam Cash - QA Representative

AUTOMATIC SWITCH COMPANY Hanover Road Florham Park, NJ 07932 Attn: QA Manager

EATON CORPORATION Cutler-Hammer Division 1349 Bryn Mawr Avenue Itasca, IL 60143 Attn: QA Manager

NORTHERN STATES POWER COMPANY 414 Nicollet Mall Minneapolis, MN 54401 Attn: QA Manager

VIRGINIA ELECTRIC POWER COMPANY P. O. Box 537 Richmond, VA 23204 Actn: QA Manager

BROWN-BOVERI GOULD INC. 4371 County Line Road Chalfont, PA 18914 Attn: QA Manager

Attachment 1 IN 82-04 March 10, 1982 Page 3 of 7

GENERAL ELECTRIC COMPANY P.O. Box 2149 1114 Old Concord Road Salisbury, NC 28144 Attn: QA Manager

FLORIDA POWER CORPORATION P.C. Box 14042 St. Petersburg, FL 33733 Attn: QA Manager

FLORIDA POWER CORPORATION P.O. Box 219 Crystal River, FL 32629 Attn: Pam Mullins

FISCHBACK LORD ELECTRIC COMPANY BOX 771 Hanford #2 Richland, WA 99352 Attn: Gordon Kittle, Purchasing Agent

WESTINGHOUSE ELECTRIC CORPORATION
SWITCHGEAR DIVISION
700 Braddock Avenue
E. Pittsburgh, PA 15112
Attn: A. S. Merrill, Switchgear Purchasing 10NN

COMSIP CUSTOMLINE 1418 E. Linden Avenue Linden, NJ 07036 Attn: QA Manager

COLT INDUSTRIES
FAIRBANKS MORSE
701 Lawton Avenue
Beloit, WI 53551
Attn: QA Manager

PHILADELPHIA ELECTRIC CO. P. O. Box 8699 2301 Market Street N3-2 Philadelphia, PA 19109 Attn: Designer in Charge

Attachment 1 IN 82-04 March 10, 1982 Page 4 of 7

BECHTEL POWER CORPORATION P.O. BOX 60860 Terminal Annex Los Angeles, CA 90060 Atts.: QA Manager

FRANK ELECTRIC CORPORATION P.O. Box 69 Willow Springs Lane Road #5 York, PA 17405 Attn: QA Manager

GENERAL ELECTRIC COMPANY P. O. Box 488 Agency Road Burlington, Iowa 52601 Attn: E. F. McMillan

TOLEDO EDISON COMPANY 300 Madison Avenue Toledo, OH 43652 Attn: QA Director

INDIANA & MICHIGAN ELECTRIC CO. P.O. BOX 60 Fort Wayne, IN 46801 Attn: QA Manager

RELIANCE ELECTRIC 4900 Lewis Road Stone Mountain, GA 30083 Attn: Ms C. Eakin

MERCURY CO. OF NORWOOD, INC. Subsidiary of Fischbach & Moore, Inc. P.O. Box 1687 10 Burke Drive Brockton, MA 02403 Attn: Lawrence P. Capron, QA Manager

NORTHEAST NUCLEAR ENERGY CO.
CONNECTICUT YANKEE ATOMIC POWER CO.
P.O. Box 270
Hartford, CT 06101
Attn: Norman Thomas (W24)

Attachment 1 IN 82-04 March 10, 1982 Page 5 of 7

LONG ISLAND LIGHTING COMPANY Old Country Road Mineola, NY 11530 Attn: QA Manager

BELOIT POWER SYSTEMS
DIVISION OF LITTON INDUSTRIES
555 Lawton Avenue
Beloit, WI 53511
Attn: Roger Churchill, Purchasing Agent

WISCONSIN PUBLIC SERVICE COMPANY 700 N. Adams Street P.O. Box 700 Green Bay, WI 54305 Attn: Purchasing Department

SHOREHAM NUCLEAR POWER STATION
P.O. Box 618
North County Road
Wading River, NY 11792
Attn: Mr. B.R. McCaffray, Project Engineer
LILCO Project Office

AMERACE N.V.
P.O. Box 13
Industrielaan Ille Industriezone
9440 - EREMBODEGEM
Belgium
Attn: Mr. Rudy De Schaepmeester

SYSTEMS CONTROL CORPORATION P.O. Box 788 NO US #2 Iron Mountain, MI 49801 Attn: QA Manager

HARLO CORPORATION CONTROL PANEL DIVISION 4210 Ferry Street Grandville, MI 49418 Attn: QA Manager

WESTINGHOUSE ELECTRIC CORPORATION GENERAL CONTROL DIVISION 3900 West 41st Street Chicago, IL 60632 Attn: QA Manager

Attachment 1 IN 82-04 March 10, 1982 Page 6 of 7

SOUTHERN CALIFORNIA EDISON COMPANY % Bechtel Power Corporation P.O. Box 450 San Clemente, CA 92672 Attn: MS Gail Walters, Field Purchasing

OMAHA PUBLIC POWER DISTRICT 1623 Harney Street Omaha, NB 68102 Attn: QA Manager

120 m

FLORIDA POWER & LIGHT COMPANY % Ebasco Backfit P.O. Box 2108 Ft. Pierce, FL. 33450 Attn: QA Manager

VERMONT YANKEE NUCLEAR POWER P.O. Box 157 Vermon, Vermont 05354 Attn: Greg Gillmore, Purchasing

VIRGINIA ELECTRIC & POWER CO. SURRY POWER STATION Route 650 Off HWY 10 Surry, VA 23883 Attn: Purchasing Agent

BECHTEL POWER CORPORATION
P. O. Box 384
Route 11 5 Miles NE of Berwick
Berwick, PA 18603
Attn: Mr. I. E. Booher

TENNESSEE VALLEY AUTHORITY 285 Haney Building Chattanooga, TN 37401 Attn: QA Manager

COMSIP 3030 Red Hat Lane Whittier, CA 90601 Attn: QA Manager

ALABAMA POWER COMPANY
P. O. BOX 2641
Birmingham, AL 35291
Attn: Mr. J.W, McGowan, QA Manager

GOULD 2002 Bethel Road Finksburg, MD 21048 Attn: QA Manager Attachment 1 IN 82-04 March 10, 1982 Page 7 of 7