

SUPPLEMENT TO DVR

DVR NO.			
STA	UNIT	YEAR	NO.
D - 12	- 2	- 81	- 109

PART 1	TITLE OF EVENT	OCCURRED	
	Damage to Horizontal Guide (1510-12) Restraining LPCI/CCSW Pipe 1510-16"	10-05-81	11:30
		DATE	TIME
REASON FOR SUPPLEMENTAL REPORT			
To update the evaluation action taken to avoid water hammer in the CCSW system.			
PART 2	ACCEPTANCE BY STATION REVIEW		
	DATE	<u>2/22/82</u>	<u>2/24/82</u>
	SUPPLEMENTAL REPORT APPROVED AND AUTHORIZED FOR DISTRIBUTION	<u>Douglas Dwyer</u> STATION SUPERINTENDENT	<u>2/25/82</u> DATE