



March 9, 1982

Log No. K82-480  
File: RR 2 (NP-33-82-09)

Docket No. 50-346  
License No. NPF-3

Mr. James G. Keppler  
Regional Administrator, Region III  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Reportable Occurrence 82-008  
Davis-Besse Nuclear Power Station Unit 1  
Date of Occurrence: February 8, 1982

Enclosed are three copies of Licensee Event Report 82-008 with a supplemental information sheet which are being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Terry D. Murray  
Station Superintendent  
Davis-Besse Nuclear Power Station

TDM/ljk

Enclosure

cc: Mr. Richard DeYoung, Director  
Office of Inspection and Enforcement  
Encl: 30 copies

Mr. Norman Haller, Director  
Office of Management and Program Analysis  
Encl: 3 copies

Mr. Luis Reyes  
NRC Resident Inspector  
Encl: 1 copy



MAR 12 1982

8203170101 820309  
PDR ADOCK 05000346  
S PDR

IE 22:11