

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

REGION II
MAR 8 4 31 PM '82

March 5, 1982

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 3 - DOCKET
NO. 50-296 - FACILITY OPERATING LICENSE DPR-68 - REPORTABLE OCCURRENCE
REPORT BFRO-50-296/82004

The enclosed report provides details concerning high-pressure coolant
injection steam line space high-temperature switches which were found
out of calibration tolerance. This report is submitted in accordance
with Browns Ferry unit 3 Technical Specification 6.7.2.b(1).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. A. Green
J. J. Green

Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Records Center
Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

OFFICIAL COPY
1822
5/1

8203170504 820305
PDR ADOCK 05000296
S PDR