



March 10, 1982

PNS-LI-82-87

54-335

Mr. James P. O'Reilly Regional Administrator Region II U.S. Nuclear Regulatory Commission 101 Marietta Stree, Suite 3100 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 335-82-06

ST. LUCIE UNIT 1

DATE OF OCCURRENCE: Februaruy 8, 1982
TEXHNICAL SPECIFICATION 4.7.10.a

## MECHANICAL SNUBBERS

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30 day notification of the subject occurrence. Although the inspection referenced in the report took place between October 19, 1981 and November 19, 1981, the failure of the snubber in this report was not determined to be reportable until February 8, 1982.

Very truly yours,

J. W. Williams, Jr.

allienis (

Vice President Nuclear Energy

PLP/ys

Attachment

cc: Director, Office of Inspection and Enforcement (30)

Harold F. Reis, Esquire

File 933.1 SL

TE 2251