

APPENDIX A  
NOTICE OF VIOLATION

Consolidated Edison Company of New York  
4 Irving Place  
New York, New York 10003  
License No. DPR-64

Based on the results of an NRC inspection on March 7-9, 1977, it appears that one of your activities was not conducted in full compliance with the conditions of your license as indicated below. This item is an Infraction.

Appendix B to Facility Operating License DPR-64, Environmental Technical Specifications (ETS) Requirements, Section 3.4.1.b requires a sample to be taken from each batch of liquid waste prior to release and analyzed in accordance with Table 2.4-1. Table 2.4-1 requires that each batch of liquid be analyzed for principle gamma emitters.

Contrary to this requirement, each batch of liquid was not analyzed for principle gamma emitters prior to discharge for the period from December, 1975 to January, 1977.

Prior to leaving the site, the inspector verified that the licensee had completed corrective action in this area and has been meeting this requirement since January, 1977.