

LONG IBLAND LIGHTING COMPANY

SHOREHAM NUCLEAR POWER STATION P.O. BOX 618, NORTH COUNTRY ROAD + WADING RIVER, N.Y. 11792

WILLIAM E. STEIGER, JR.
ASSISTANT VICE PRESIDENT-NUCLEAR OPERATIONS

SNRC-1714

APR 2 7 1990

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D.C. 20555

NRC Bulletin No. 90-02
Loss of Thermal Margin Caused
By Channel Box Bow
Shoreham Nuclear Power Station - Unit 1
Docket No. 50-322

Gentlemen:

The Long Island Lighting Company (LILCO) has reviewed Bulletin 90-02 as it relates to the Shoreham Nuclear Power Station (SNPS). The channel boxes in the Shoreham reactor have never completed a single bundle lifetime of normal use, apart from low power testing equivalent to approximately two (2) effective full power days (EFPD). Further, in accordance with the LILCO/New York State Settlement Agreement and the defueled and non-operating status of the plant, LILCO will not use the channel boxes for a second bundle lifetime. Therefore, Bulletin 90-02 does not apply to SNPS.

If additional information or follow up discussion is required, please do not hesitate to contact my office.

Very truly yours,

W. E. Steiger, Jr.

Wither

Assistant Vice President

Nuclear Operations

MP/ap

cc:

S. Brown

T. T. Martin

L. Doerflein

9005030177 900427 PDR ADOCK 05000322 PDC JE38