

In Reply Refer To:
Licenses: 35-21035-01
 35-21035-02
Dockets: 030-19696/90-01
 030-19802/90-01

MAY 9 1990

Oklahoma Medical Center
ATTN: Andy Lasser
 Administrator
P.O. Box 26307
Oklahoma City, Oklahoma 73126

Gentlemen:

This refers to the routine, unannounced radiation safety inspection conducted by Mr. Selvan Rajendran of this office on March 7-9, 1990, of the activities authorized by NRC Byproduct Material License Nos. 35-21035-01 and 35-21035-02, and to the discussion of our findings held by the inspector with members of your staff at the conclusion of the inspection.

The inspection was an examination of the activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, independent measurements, and observations by the inspector.

For License No. 35-21035-01, certain of your activities were found not to be conducted in full compliance with NRC requirements. Consequently, you are required to respond to this matter in writing, in accordance with the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Your response should be based on the specifics contained in the Notice of Violation enclosed with this letter. No violations of NRC requirements were found during this inspection for License No. 35-21035-02.

The inspector also reviewed the actions you had taken with respect to the violation observed during our previous inspection of License No. 35-21035-02 which was conducted on May 26, 1989. He verified that the corrective actions for this violation had been implemented.

The inspector noted, in general, that the radiation safety program appears to be adequate. The violations that were identified by the inspector indicate that there is a lack of attention to NRC regulations. Consequently, in your reply to this letter, you should describe those specific actions planned or taken to improve the effectiveness of the management control of your licensed operations, with particular emphasis on measures currently being taken to prevent further violations.

RIV:NMIS
SRajendran:lm
5/8/90

C:NMIS
CLCain
5/8/90

D:DRSS
ABBeach
5/8/90

9005150155 900509
REG4 LIC30
35-21035-01 PDC

TEO?
11

The response directed by this letter and the accompanying Notice is not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

Should you have any questions concerning this letter, we will be pleased to discuss them with you.

Sincerely,

Original Signed By:

A. B. BEACH

A. Bill Beach, Director
Division of Radiation Safety
and Safeguards

Enclosure:

Appendix - Notice of Violation

cc:

Oklahoma Radiation Control Program Director

bcc:

DMB - Original (IE-07)

RD Martin

AB Beach

LAYandell

MRodriguez, OC/LFDCB (4503)

*CLCain

*WLFisher

*SRajendran

*NMIS

*MIS System

*RIV Files (2)

*RSTS Operator

*REHall, URFO

*W/766