

APR 9 1974

In Reply Refer To:
RO:II:RCP
50-324/74-5

Carolina Power and Light Company
Attn: Mr. J. A. Jones
Executive Vice President
Engineering, Construction
and Operations
336 Fayetteville Street
Raleigh, North Carolina 27602

Gentlemen:

This refers to the inspection conducted by Mr. R. C. Parker of this office on March 25-27, 1974, of activities authorized by AEC Construction Permit No. CFFR-67 for the Brunswick 2 facility, and to the discussion of our findings held by Mr. R. C. Parker with Mr. E. G. Hollowell at the conclusion of the inspection.

Areas examined during the inspection and our findings are discussed in the enclosed inspection report. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the inspector.

The results of our followup of previously identified matters are contained in the enclosed report as follows:

The status of unresolved items identified in previous inspection reports is discussed in Section IV of the summary of the enclosed report.

New unresolved items are identified in Section III of the summary of the enclosed report.

During the inspection it was found that certain activities under your license appear to be in violation of Appendix B to 10 CFR 50 of the AEC Regulations, "Quality Assurance Criteria for Nuclear Power Plant." The violations and references to the pertinent requirements are identified in Section I of the summary of the enclosed report.

Carolina Power and Light
Company

-2-

APR 19 1974

This notice is sent to you pursuant to the provisions of Section 2.201 of the AEC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office, within 20 days of your receipt of this notice, a written statement or explanation in reply including: (1) corrective steps which have been taken by you, and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved.

In accordance with Section 2.790 of the AEC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the AEC's Public Document Room. If this report contains any information that you believe to be proprietary, it is necessary that you submit a written application to this office requesting that such information be withheld from public disclosure. If no proprietary information is identified, a written statement to that effect should be submitted. If an application is submitted, it must fully identify the bases for which information is claimed to be proprietary. The application should be prepared so that information sought to be withheld is incorporated in a separate paper and referenced in the application since the application will be placed in the Public Document Room. Your application, or written statement, should be submitted to us within 20 days. If we are not contacted as specified, the enclosed report and this letter may then be placed in the Public Document Room.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Very truly yours,

Original Signed by
N. C. Moseley

Norman C. Moseley
Director

Enclosure:
RO Inspection Report No.
50-324/74-5

OFFICE ▶	RO:IX	RO:II	RO:II			
SURNAME ▶	RCParker:kk	W.C. Lewis	NCMoseley			
DATE ▶	4/8/74	4/8/74	4/ /74			

Ltr to Carolina Power and Light Company
dtd APR 19 1974

DISTRIBUTION:

H. D. Thornburg, RO

RO:HQ (4)

Directorate of Licensing (4)

DR Central Files

*PDR

*Local PDR

*NSIC

*DTIE, OR

*State

*To be dispatched at a later date

Carolina Power and Light Company
Brunswick 2

APR 18 1974

RO Inspection Report No. 50-324/74-5

cc w/encl:

H. D. Thornburg, RO

RO:HQ (5)

DR Central Files

Regulatory Standards (3)

Directorate of Licensing (13)

cc encl. only:

*PDR

*Local PDR

*NSIC

*DTIE, OR

*State

*To be dispatched at a later date