



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-8064

JUN 29 1993

Dockets: 50-313
50-368
Licenses: DPR-51
NPF-6

Entergy Operations, Inc.
ATTN: J. W. Yelverton, Vice President
Operations, Arkansas Nuclear One
Route 3, Box 137G
Russellville, Arkansas 72801

SUBJECT: NRC INSPECTION REPORT 50-313/93-13; 50-368/93-13

This refers to the inspection conducted by Mr. M. Runyan and the inspectors identified in the enclosed report dated May 17-21, 1993. The inspection included a review of activities authorized for your Arkansas Nuclear One facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report. A followup exit meeting was held at the facility on June 18, 1993, with Mr. Sellman and other members of your staff to further discuss the findings from the inspection.

This inspection examined the implementation of the program you developed to meet your commitments to Generic Letter 89-10, "Safety-Related Motor-Operated Valve Testing and Surveillance." The inspection consisted of interviews with personnel and selective examination of records and procedures. We considered the implementation of your motor-operated valve program to be generally in accordance with your commitments to Generic Letter 89-10.

During the inspection, you committed to review the diagnostic traces of all completed differential pressure tests to verify correct placement of software marks and to ensure that the assumed test conditions were achieved. You also committed to initiate a second-engineer review of diagnostic traces, post-test evaluations, and diagnostic test data sheets. If our understanding of these commitments is incorrect, please inform us immediately.

For clarification, inspection followup items have been established for site-specific issues and will be separately tracked for closure. Generic issues identified in the enclosed report will be inspected as a part of Generic Letter 89-10, Phase 2 inspection closeout.

As a result of information reviewed during this inspection, we have accepted your request of March 19, 1993, to extend your committed date for completion of the recommendations of Generic Letter 89-10.


9307060020 930629
PDR ADOCK 05000313
G PDR

JED

In accordance with 10 CFR Part 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,



Samuel J. Collins, Director
Division of Reactor Safety

Enclosure:

Appendix- NRC Inspection Report
50-313/93-13; 50-368/93-13

Entergy Operations, Inc.
ATTN: Donald C. Hintz, President &
Chief Operating Officer
P.O. Box 31995
Jackson, Mississippi 39286

Entergy Operations, Inc.
ATTN: John R. McGaha, Vice President
Operations Support
P.O. Box 31995
Jackson, Mississippi 39286

Wise, Carter, Child & Caraway
ATTN: Robert B. McGehee, Esq.
P.O. Box 651
Jackson, Mississippi 39205

Entergy Operations, Inc.
ATTN: James J. Fisicaro
Director, Licensing
Route 3, Box 137G
Russellville, Arkansas 72801

Entergy Operations, Inc.
ATTN: Michael B. Sellman, General
Manager, Plant Operations
Route 3, Box 137G
Russellville, Arkansas 72801

Honorable Joe W. Phillips
County Judge of Pope County
Pope County Courthouse
Russellville, Arkansas 72801

Winston & Strawn
ATTN: Nicholas S. Reynolds, Esq.
1400 L Street, N.W.
Washington, D.C. 20005-3502

Arkansas Department of Health
ATTN: Ms. Greta Dicus, Director
Division of Radiation Control and
Emergency Management
4815 West Markham Street
Little Rock, Arkansas 72201-3867

B&W Nuclear Technologies
ATTN: Robert B. Borsum
Licensing Representative
1700 Rockville Pike, Suite 525
Rockville, Maryland 20852

Admiral Kinnaird R. McKee, USN (Ret)
214 South Morris Street
Oxford, Maryland 21654

ABB Combustion Engineering
Nuclear Power
ATTN: Charles B. Brinkman
Manager, Washington
Nuclear Operations
12300 Twinbrook Parkway, Suite 330
Rockville, Maryland 20852

bcc to DMB (IE01)

bcc distrib. by RIV:

J. L. Milhoan
 Lisa Shea, RM/ALF, MS: MNBB 4503
 DRSS-FIPS
 Project Engineer (DRP/D)
 R. Vickrey
 T. Scarbrough, NRR
 P. Eapen, RI
 D. Danielson, RIII

Resident Inspector
 Section Chief (DRP/D)
 MIS System
 RIV File
 Section Chief (DRP/TSS)
 M. Runyan
 T. Westerman
 A. Trusty, EG&G Idaho
 F. Jape, RII
 W. Ang, RV

*RIV:ES <i>DM</i>	*RIV:ES <i>DM</i>	*C:ES <i>DM</i>	DD:DRS <i>DM</i>	EMED;NRR	D:DRP <i>DM</i>	D:DRS <i>DM</i>
MFRunyan/lb	RBVickrey	TFWesterman	ATHowell	JNorberg	ABBeach <i>DM</i>	SJCollins <i>DM</i>
6/3/93	6/3/93	6/4/93	6/13/93	6/18/93	6/22/93	6/27/93

*Previously Concurred

bcc to DMB (IE01)

bcc distrib. by RIV:

J. L. Milhoan
 Lisa Shea, RM/ALF, MS: MNBB 4503
 DRSS-FIPS
 Project Engineer (DRP/D)
 R. Vickrey
 T. Scarbrough, NRR
 P. Eapen, RI
 D. Danielson, RIII

Resident Inspector
 Section Chief (DRP/D)
 MIS System
 RIV File
 Section Chief (DRP/TSS)
 M. Runyan
 T. Westerman
 A. Trusty, EG&G Idaho
 F. Jape, RII
 W. Ang, RV

*RIV:ES <i>DMB</i>	*RIV:ES <i>DMB</i>	*C:ES <i>DMB</i>	DD:DRS <i>gls</i>	EMED;NRR	D:DRP <i>gls</i>	D:DRS <i>gls</i>
MFRunyan/lb	RBVickrey	TFWesterman	ATHowell	JNorberg	ABBeach <i>gls</i>	SJCollins <i>gls</i>
6/3/93	6/3/93	6/4/93	6/23/93	6/29/93	6/29/93	6/29/93

*Previously Concurred