

DCD/DCB

JUL 08 1993

University of Michigan
ATTN: William B. Krumm, Associate
Vice President for
Business Operations
5010 Fleming Administration Building
Ann Arbor, MI 48109

License No. 21-00215-04
Docket No. 030-01988

Re: Mr. Krumm:

This refers to the special safety inspection conducted by Michael Kurth of this office on April 12 through June 3, 1993, of activities authorized by NRC Byproduct Material License No. 21-00215-04, and to the discussion of our findings with Mark Driscoll and Dr. Robert Gray at the conclusion of the inspection. The inspection included a review of the radiation safety training program implemented at the Henry F. Vaughan Building.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Roy J. Caniano, Chief
Nuclear Materials Safety Branch

cc: Mark Driscoll, RSO

bcc: PUBLIC

RIII
Kurth/bt
07/7/93

RIII
Shear
7/7/93

RIII
Caniano
7/8/93

1E07
PUBLIC 1/0

9307220103 930708
PDR ADOCK 03001988
C PDR