



Department of Energy  
Albuquerque Field Office  
P.O. Box 5400  
Albuquerque, New Mexico 87185-5400

JUL 21 1993

Mr. John J. Surmeier  
Chief, Uranium Recovery Branch  
Division of Low-Level Waste  
Management and Decommissioning  
Office of Nuclear Materials Safety  
and Safeguards  
Mail Stop 5E-4 OWFN  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Dear Mr. Surmeier:

Enclosed for your review and comment are six copies of an addendum to Attachment 3, Groundwater Hydrology Report, of the preliminary final Remedial Action Plan and Site Design for Stabilization of the Inactive Uranium Mill Tailings Site at Maybell, Colorado, transmitted to you on June 25, 1993. This addendum, entitled Maybell UMTRA Site Groundwater Quality by Location, contains all the groundwater quality data that has been collected.

If you have any questions regarding this transmittal, please contact me at (505) 845-5637.

Sincerely,

Woody Woodworth  
Site Manager  
Uranium Mill Tailings Remedial Action  
Project Office

Enclosure (6)

cc w/o enclosure:

D. Gillen, NRC  
C. Smythe, UMTRA  
S. Hamp, UMTRA  
W. Woodworth, UMTRA  
D. Bierley, TAC  
J. McBee, TAC

9307230288 930721  
PDR WASTE  
WM-69 PDR

1/2  
WM-69  
NL16