



**CENTERIOR
ENERGY**

Louis F. Storz
Vice President - Nuclear
Davis-Besse

300 Madison Avenue
Toledo, OH 43652-0001
(419)249-2300

Document Number 50-346

License Number NPF-3

Serial Number 2156

July 29, 1993

United States Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Subject: Summary Report for Eighth Refueling Outage Inservice
Inspection Activities
Davis-Besse Nuclear Power Station - Unit 1

Gentlemen:

In accordance with the 1986 Edition of the American Society of
Mechanical Engineers (ASME) Boiler and Pressure Vessel Code Section XI,
IWA-6000, enclosed is the subject report covering inservice inspection
activities, and repairs and replacements completed through the end of
the Davis-Besse Nuclear Power Station, Unit 1 eighth refueling outage.

Should you have any questions regarding the enclosed reports, please
call Mr. Dale R. Wuokko, Manager - Regulatory Affairs (Acting), at
(419) 249-2366.

Very truly yours,

PWS/dlc

Enclosure

cc: J. B. Hopkins, NRC Region III, DB-1 NRC Senior Project Manager
J. B. Martin, Regional Administrator, NRC Region III
S. Stasek, NRC Region III, DB-1 Senior Resident Inspector
Hartford Steam Boiler and Insurance Company (2)
State of Ohio
Utility Radiological Safety Board

Operating Companies
Cleveland Electric Illuminating
Toledo Edison

9308050074 930729
PDR ADDCK 0500346
G PDR

A047
11