



## Northern States Power Company

414 Nicollet Mall Minneapolis, Minnesota 55401 Telephone (612) 330-5500

February 24, 1982

Regional Administrator Region III U S Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137



PRAIRIE ISLAND NUCLEAR GENERATING PLANT Docket No. 50-306 License No. DPR-60

One Unit 2 Delta T Protection Setpoint Found Out of Spec

The Licensee Event Report for this occurrence is attached.

This event is reported in compliance with Technical Specification 6.7.B.2.a since it represents an instrument setting less conservative than required by the Technical Specifications. The functional requirements of the system would have been fulfilled, however.

Dail Mussel For

L O Mayer, PE Manager of Nuclear Support Services

LOM/DMM/bp

Attachment

cc NRC Document Control Desk (1)
NRC Resident Inspector
MPCA
Attn: J W Ferman

TF 22 FEB 2 6 1982