
## ##XXX.E.F18=\7\C.A. f1.8.8\*E.A.18



P.O. BOX 270 HARTFORD, CONNECTICUT 06101 (203) 666-691;

March 30, 1982 MP-2- 5104

Mr. Ronald C. Haynes Regional Administrator, Region 1 Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, Pennsylvania 19406

Reference:

Facility Operating License No. DPR-65

Docket No. 50-336

Reportable Occurrence RO-50-336/81-40/3X-1

Dear Mr. Haynes:

This letter forwards Licensee Event Report 81-40/3X-1 required to be submitted within thirty days pursuant to Millstone Unit 2 Appendix A Technical Specifications, Section 6.9.1.9.b, conditions leading to operation in a degraded mode permitted by a limiting condition for operation. This update report provides additional information for the cause of the event. An additional three copies of the report are enclosed.

Yours truly,

NORTHEAST NUCLEAR ENERGY COMPANY

J. Mroczka Station Superintendent Millstone Nuclear Power Station

EJM/JGR:mo

Attachment: LER RO-81-40/3X-1

cc: Director, Office of Inspection and Enforcement, Washington, D.C. (30) Director, Office of Management Information and Program Control,

Washington, D.C. (3)

U.S. Nuclear Regulatory Commission, c/o Document Management Branch,

Washington, D.C. 20555

8204070324 820330 PDR ADDCK 05000336