

John D. O'Toole
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003
Telephone (212) 460-2533

March 24, 1982

Re: Indian Point Unit No. 2
Docket No. 50-247
LER-82-010/01T-0

Mr. Ronald C. Haynes, Regional Administrator
Office of Inspection and Enforcement
Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA. 19406



Dear Mr. Haynes:

The attached Licensee Event Report LER-82-010 is hereby submitted in accordance with the requirements of Technical Specification 6.9.1.7. This event is of the type described in Technical Specification 6.9.1.7.1.f.

Three copies of this letter and the attachment are enclosed as required.

Very truly yours,

John D. O'Toole

Attach.

CC: Mr. Richard DeYoung, Director (30 copies)
Office of Inspection and Enforcement
c/o Distribution Services Branch, DDC, ADM
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. William G. McDonald, Director (3 copies)
Office of Management Information and Program Control
c/o Distribution Service Branch, DDC, ADM
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. T. Rebelowski, Senior Resident Inspector
U.S. Nuclear Regulatory Commission
Post Office Box 38
Buchanan, New York 10511

8204080105 820324
PDR ADOCK 05000247
S PDR

IER2
04/1