

PHILADELPHIA ELECTRIC COMPANY


2301 MARKET STREET

P.O. BOX 8699

PHILADELPHIA, PA. 19101

(215) 841-5001

SHIELDS L. DALTROFF
VICE PRESIDENT
ELECTRIC PRODUCTION



April 5, 1982

Docket Nos. 50-277
50-278

Mr. John F. Stolz, Chief
U.S. Nuclear Regulatory Commission
Operating Reactors Branch #4
Division of Licensing
Washington, DC 20555

Dear Mr. Stolz:

Your letter of March 5, 1982 requested additional information on the Peach Bottom Inservice Inspection Program. Due to the significant amount of research required to address the subject with a complete and satisfactory response, we must request an extension for its submittal. Peach Bottom Unit 2 is presently undergoing an extended refueling and modifications outage which requires significant attention by the same staffs involved in preparing our response to your request.

A telephone conversation with the NRC Peach Bottom Project Manager on March 29, 1982, described the subject and an extension to June 8, 1982, was mutually determined to be appropriate.

If you have any further questions or require additional information, please do not hesitate to contact us.

Very truly yours,

A001
s
1/0