

MAR 22 1982

Docket Nos. 50-272
50-311

Public Service Electric and Gas Company
ATTN: Mr. Richard A. Uderitz
Vice President - Nuclear
Mail Code T15A
P. O. Box 570
Newark, New Jersey 07101



Gentlemen:

Subject: Inspection No. 50-272/82-07 and 50-311/82-06

This refers to the routine safety inspection conducted by Mr. E. T. Shaub of this office on February 8-11 and 17-18, 1982 at the Salem Nuclear Generating Station, Hancock's Bridge, New Jersey and at your Newark, New Jersey corporate office of activities authorized by NRC License Nos. DPR-70 and DPR-75 and to the discussions of our findings held by Messrs. Shaub and Meyer with Messrs. J. Driscoll, J. Boettger, R. Mittl, and other members of your staff at the conclusion of the inspection.

Areas examined during this inspection are described in the NRC Region I Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Our inspector also verified the steps you have taken to correct the items of noncompliance brought to your attention in letters dated May 6, 1980 (Item A) and July 24, 1981 (Item A). We have no further questions regarding the steps you took to correct Item A of the May 6, 1980 letter. With regard to Item A in the July 24, 1981 letter, this was not fully corrected.

Based on the results of this inspection, it appears that one of your activities was not conducted in full compliance with NRC requirements, as set forth in the Notice of Violation, enclosed herewith as Appendix A. This item of noncompliance has been categorized into the levels described in the Federal Register Notice (45 FR 66754) dated October 7, 1980. You are required to respond to this letter and in preparing your response, you should follow the instructions in Appendix A.

RI:DEPOS
Shaub/gwc
3/12/82

Ta
3/15

RI:DEPOS
Meyer

gm
3/15

RI:DETP
Napuda

(Signature)

RI:DETP
Capton

OFFICIAL RECORD COPY

MC
3/17

EBMETER
3/18

1001
5
11

In addition, the attached inspection report identifies four unresolved items, three of which concern the manner in which you meet some of the administrative control requirements of the Technical Specifications. In your response to this letter please address these unresolved items and specifically state the actions you are taking to resolve these items, the proposed schedule for these actions, and the measures taken in the interim to assure you effectively implement the administrative control requirements of the Technical Specifications.


In accordance with 10 CFR 2.790(a), a copy of this letter and the enclosures will be placed in the NRC Public Document Room unless you notify this office, by telephone, within ten days of the date of this letter and submit written application to withhold information contained therein within thirty days of the date of this letter. Such application must be consistent with the requirements of 2.790(b)(1). The telephone notification of your intent to request withholding, or any request for an extension of the 10 day period which you believe necessary, should be made to the Supervisor, Files, Mail and Records, USNRC Region I, at (215) 337-5223.

The responses directed by this notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

Your cooperation with us in this matter is appreciated.

Sincerely,^{rf}

Original Signed By: *S. Ebneler*

 Thomas T. Martin, Director
Division of Engineering and
Technical Programs

Enclosures:

1. Appendix A, Notice of Violation
2. Combined NRC Region I Inspection Report Number 50-272/82-07 and 50-311/82-06

cc w/encl:

R. L. Mittl, General Manager - Corporate QA
H. J. Midura, General Manager - Salem Operations
E. A. Liden, Manager - Nuclear Licensing and Regulation
R. Fryling, Jr., Esquire
Public Document Room (PDR)
Local Public Document Room (LPDR)
Nuclear Safety Information Center (NSIC)
State of New Jersey
NRC Resident Inspector

bcc w/encl:

Region I Docket Room (with concurrences)
Chief, Operational Support Section (w/o encls)
E. Greenman, RI