## MAR 2 6 1982

Docket No. 50-346

Toledo Edison Company ATTN: Mr. Richard P. Crouse


Vice President

Nuclear

Edison Plaza 300 Madison Avenue Toledo, OH 43652

on March 1, 1982.





The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in noncompliance with NRC requirements, as specified in the enclosed Appendix. A written response, submitted under oath or affirmation, is required.

During our review of the BWST overtemperature condition, we noted an apparent lack of awareness on the part of your operating staff to recognize operating conditions contained in your FSAR. This concern was discussed with your corporate and site personnel during a meeting held on January 27, 1982 in the Region III office. During this meeting we indicated that problems identified in areas not specifically addressed in the Technical Specifications that have safety significance should be brought to the attention of upper levels of management. Therefore, in your response to the item of noncompliance, please include the actions you plan to take to ensure that the proper levels of management are informed when these problems are identified.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC's Public Document Room. If this report contains any information



that you (or your contractors) believe to be exempt from disclosure under 10 CFR 9.5(a)(4), it is necessary that you (a) notify this office by telephone within ten (10) days from the date of this letter of your intention to file a request for withholding; and (b) submit within twenty-five (25) days from the date of this letter a written application to this office to withhold such information. If your receipt of this letter has been delayed such that less than seven (7) days are available for your review, please notify this office promptly so that a new due date may be established. Consistent with Section 2.790(b)(1), any such application must be accompanied by an affidavit executed by the owner of the information which identifies the document or part sought to be withheld, and which contains a full statement of the reasons which are the bases for the claim that the information should be withheld from public disclosure. This section further requires the statement to address with specificity the considerations listed in 10 CFR 2.790(b)(4). The information sought to be withheld shall be incorporated as far as possible into a separate part of the affidavit. If we do not hear from you in this regard within the specified periods noted above, a copy of this letter, the enclosures, and your response to this letter will be placed in the Public Document Room.

The responses directed by this letter (and the accompanying Notice) are not subject to the clearance procedures of the Office of Management and Budget a required by the Paperwork Reduction Act of 1980, PL 96-511.

Sincerely,

"Original Signed by C.E. Morellus"

C. E. Norelius, Director Division of Engineering and Technical Programs

Enclosures:

Appendix, Notice
 of Violation
Inspection Report
 No. 50-346/82-07(DETP)

cc w/encls:

T. D. Murray, Station Superintendent DMB/Document Control Desk (RIDS) Resident Inspector, RIII Harold W. Kohn, Power Siting Commission

Helen W. Evans, State of Ohio

Robinson/so 2/24/82 RIII Nelson 3/24 RILL

Notelius