MAR 1 4 1982

Florida Power and Light Company ATTN: Dr. R. E. Uhrig, Vice President Advanced Systems and Technology P. O. Box 529100 Miami, FL 33152

Gentlemen:

Subject: Report Nos 50-250/82-10 and 50-251/82-10

This refers to the routine safety inspection conducted by Mr. P. A. Taylor of this office on February 24, 1982, of activities authorized by NRC Operating License Nos. DPR-31 and DPR-41 for the Turkey Point facility and to the discussion of our findings held with Mr. D. W. Haase, Operations Superintendent, at the conclusion of the inspection.

Areas examined during the inspection and our findings are discussed in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no violations or deviations were disclosed.

In accordance with 10 CFR 2.790(a), a copy of this letter and the enclosure will be placed in the NRC's Public Document Room unless you notify this office, by telephone, within ten days of the date of this letter and submit written application to withhold information contained therein within thirty days of the date of this letter. Such application must be consistent with the requirements of 2.790(b)(1).

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

F. J. Long, Acting Chief Reactor Projects Branch 2 Division of Project and Resident Programs

Enclosure: (See Page 2)

IEO!

Florida Power and Light Company

.

-

2

Enclosure: Inspection Report Nos. 50-250/82-10 and 50-251/82-10

cc w/encl: H. E. Yaeger, Site Manager

bcc w/encl: NRC Resident Inspector Document Management Branch State of Florida

RII Playlor:ejw 3/24/82







