



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

February 16, 1982

W3K-82-0092
Q-3-T33

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

Mr. John Woodward
Factory Mutual Engineering
12 Perimeter Center East, Northwest
Suite 1200
Atlanta, GA 30346

Mr. J. W. Morvant
Louisiana Department of Labor
P. O. Box 44063
Baton Rouge, LA 70804


Subject: Waterford SES Unit #3
Repair Program for the Steam Generator Tube Plugging

Re: Docket No. 50-382

Gentlemen:



Enclosed is the repair program for the Waterford SES Unit #3 Steam Generator tube plugging. This program has been reviewed by Louisiana Power & Light Company in conjunction with Ebasco Services, Inc. and found acceptable. This repair program is submitted for your review as required in paragraph IWA4130 of the ASME Section XI Code. If there are any questions regarding this ongoing activity, please advise.

Very truly yours,


T. F. Gerrets
Quality Assurance Manager

TFG:RAH:grf

cc: L. L. Bass, W. M. Morgan, J. Woods, L. A. Stinson, L. V. Maurin,
D. B. Lester, R. K. Stampely, R. Hartnett, P. V. Prasankumar,
F. J. Drummond, Central Records, Nuclear Records



8205030 467

IESI
5
1/1