DCS No: 050322-820427 Date: April 28, 1982

## PRELIMINARY NOTIFICATION OF EVENT OR UNUSUAL OCCURRENCE--PNO-I-82-34

This preliminary notification constitutes EARLY notice of events of POSSIBLE safety or public interest significance. The information is as initially received without verification or evaluation, and is basically all that is known by the Region I staff on this date.

Facility:Long Island Lighting Company	Licensee Emergency Classification:				
Shoreham Nuclear Power Station (DN Shoreham, New York					

Subject: IMPERSONATION OF NRC INSPECTOR

On the morning of April 27, 1982, a male contractor employee approached two female security force trainees on the site and he asked them where certain site facilities were located. He claimed to be an NRC inspector. The two security force trainees reported the incident to their supervisor and a security consultant, who then informed the NRC Resident Inspector. The licensee Security Supervisor was able to identify and interview the individual. The individual would neither confirm nor deny that he had claimed to be an NRC inspector.

Region I reported the incident to the FBI Office, Hauppauge, N.Y. An FBI investigation is in progress.

Media interest is expected due to sensitivity to nuclear power issues in the area. No press release is planned by the NRC. The State of New York has been informed.

NRC Region I (Philadelphia) received initial notification of this event by telephone from the Resident Inspector on April 27, 1982. Further information was supplied to Region I by the licensee on April 28, 1982. The Information Assessment Team has been notified by Region I.

CONTAC		iggins 929-3311	R. Gallo 488-1234		Shepherd 8-1339			
DISTRIBUTION: H. St. Chairman Pall Comm. Gilinsk Comm. Ahearne Comm. Roberts	an Palladino Gilinsky Ahearne	MNBB EDO PA MPA ELD	Phillips 3.35 NRR	OIA AEOD		2000 S.L. C. L. L. C.	DM:DMB OT:Trans. Onl	0n1y
ACRS SECY CA		Ai SP	r Rights	INPO DO A	OT SEND			
PDR	Regiona	1 Offices		TMI R	Resident Section esident Office	houhand 1	T.f.53:35	

8205040055

Region I Form 83 (Rev. March, 1982)

TE34